

**ACM Body & Frame, Inc.**  
 2407 S IH-35, Suite 120  
 San Marcos, TX, 78666  
 Tel: 512-392-2639 Fax: 512-392-2839  
 acm-est@centurytel.net

***Estimate - Preliminary***

**Estimate Prepared by:** David Emshoff

**Appraised for:**

Accident Date:

Date of Loss:

Date: 4/27/2015

Arrival Date:

Estimate#:

Type of Loss:

Policy Number:

Claim Number:

**Insured:**

Company: City of San Marcos  
 Contact: Erin Clewell  
 Address: 2300 IH 35 South  
 City, State, Zip Code: San Marcos, Texas 78666  
 Telephone, Fax: 512-754-2203, 512-392-1187

Year	Make	Model	Color	Trim				
2012	BAE	CAIMAN	BEIGE					
Unit Number	License Plate #	Mileage	Serial#/VIN#					
POLICE RESCUE UNIT								
Sup	Seq	Labor Type	Labor Op	Description	Part Type	Part Number	Dollar Amount	Labor Units
	1			**** BODY ****				*
	2	Body	Rem/Ins	R AND I LIGHTS AND HARDWARE. INSTALL NEW STEP.	Exist			12.0*
	3	Body	Repair	PREP TIME FOR PAINT	Exist			17.0*
	4	Body	Rem/Rep	BEDLINER SUPPLIES	New		\$985.00	*
	5	Body	Ref	REFINISH UNIT WITH BEDLINER (inc new step)	Exist			39.0*
	6			**** WHEELS ****				*
	7	Ref	Ref	PREP AND PAINT WHEELS FLAT BLACK	Exist			6.0*
	8			**** SIDE PANELS ****				*
	9	Body	Rem/Rep	FABRICATE AND INSTALL ON LEFT AND RIGHT REAR WALLS 2 (2' X 8') WHITE PANELS TO ACCOMODATE GRAPHICS	New		\$111.00	4.0*
	10			**** customer to furnish graphics ****				*

Sup	Seq	Labor Type	Labor Op	Description	Part Type	Part Number	Dollar Amount	Labor Units
	11			Shop Materials			\$250.00	*
	12			Hazardous Waste			\$38.22	*
	13			Paint Materials			\$174.00	

\* - Judgement Item  
# - Labor Note Applies

#### Labor

Body	72.0	Hrs @	\$65.00	\$4,680.00
Refinish	6.0	Hrs @	\$65.00	\$390.00
Labor Total				<u>\$5,070.00</u>

#### Parts

Parts Subtotal	\$1,096.00
Less Adjustments	
Parts Total	<u>\$1,096.00</u>

#### Additional Costs and Operations

Addl. Costs/Ops Total	\$462.22
-----------------------	----------

#### Tax

#### Totals

Sub Total:	\$6,628.22
Customer Resp.	<u>\$0.00</u>
<b>Net Total</b>	<b><u>\$6,628.22</u></b>

The above is an estimate based on our inspection and does not cover any additional parts or labor which may be required after the work has started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above prices are not guaranteed. Quotations on parts and labor are current and subject to change.

*This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.*

*TruckEst does not automatically include items required by many business repair partners. This application allows the author to manually enter line items such as overlap deductions.*

2012 BAE CAIMAN