


GENERAL NOTES:

[illegible][illegible]

(15) Do not use public printers, mailers or glass that will shrinkage, bleed or otherwise damage the project. Each team shall be responsible for verifying the materials they are using comply with manufacturer's printed instructions for their use.

¹ *Journal of Management Studies* 1996, 33, 103-117.

ABBREVIATIONS

[illegible]

VICINITY MAP



CONTACT INFORMATION

Owner: Fred Bost
PH: (512) 753-9760

Establishment
Owner:

Escar Hernandez
210 :H 35 South,
Contact: Shirley
PH: (812)567.3688

A FILE NUMBER

INSULATION OF EXISTING BUILDING
CURRENTLY A VACANT BUILDING
SUBJECTS CHECK NOT REQUIRED

INDEX TO DRAWINGS

ARCHITECTURAL

A-1 SITE PLAN
A-2 FLOOR PLAN / REFLECTED CEILING PLAN
A-3 BUILDING SECTIONS
A-4 EXTERIOR ELEVATIONS
A-5 A D A PLAN

ENGINEERS

HOOD-1
HOOD-2
M-1 A-C PLAN
M-2 A-C NOTES
E-1 ELECTRICAL
EP-1 ELECTRICAL AND PLUMB NOTES
P-1 PLUMBING PLAN

SCOPE OF WORK

LO. REGIONS OF THE EASTERN COMMERCIAL, BUILDING AND A

[illegible]

SQUARE FOOTAGE		377.64 SF
PERMANENT FLOOR AREA		377.64 SF
TOTAL AREA		377.64 SF
TOTAL COST		\$45,581.16
TOTAL CONDITIONED		400.00 SF
GROSS AREA		400.00 SF

TOMA TACO RESTAURANT

178 S. 1st AVE. SAN MARCOS, TEXAS

BURTON M. ISON

WIMBORLEY, TEXAS
2805 N. 10th ST.
726-847-0250

ARCHITECT

A-1

DATE: 11-11-2009
TIME: 11:00 AM
BY: [Signature]
FOR: [Signature]
BY: [Signature]
FOR: [Signature]